



Wiring Harness




TO CONTROL
CABINET




AMP 206708-1
CONNECTOR

4 CONDUCTOR
22 AWG




AMP T 18
CONNCTR




ENCODER

2 CONDUCTOR
18 AWG



MOTOR

Motor Mounting



Slots for mounting motor allow for proper belt tensioning and small design error.

1. E-mail me the CAD file for the motor mount.
(Easy to modify the existing template part)
2. Give me a drawing with dimensions for the motor location.

You Must

1. Solder wiring harness together (2X)
 - Pick up parts and do it yourself
 - Use tools during office hours (crimping, soldering, wire stripping)
2. Give me information on motor mounting
 - Send me the CAD file
 - Give me a drawing